


3-Axis Stepping Motor Driver

(Model:TB6560T3V1) Rev1.5 2/23/2010



by

Marco K. Wong

Copy Rights Annex Depot Inc. 2010

The TB6560T3V1 is a high performance 3 Axis (X,Y,Z) CNC stepping motor controller/driver. It built-in a spindle relay and all input/output are optical isolated from the external circuit that providing 'noise' free environment. The card support Mach2, Mach3, KCam, EMC2. It can be applied to a CNC machine or upgrade an old CNC machine with this card to take advantage of new technology. It works well for a CO2 laser machine to do cutting (software dependable)


Features:

- * Optical isolation for data In/Out
- * Relay control for spindle (or laser)
- * Four step speed setting
- * High current output 3A in average
- * Big Heat sink support without heat concern.

Specification:


- * In/Out Interface port: Parallel
- * Built in relay control for spindle
- * Support 2/4 phases 4, 6, 8 wires stepping motor
- * High speed optical isolation coupling
- * Built in No. 4 Axis interface for expansion
- * LED indicators for each axis & relay
- * Current: 2.5A r.m.s (3.5A max)
- * Resolution (speed): 1/16, 1/8, 1/2, 1
- * Power: Single DC12 ~ 32V (no separated 5V needed)
- * RC7414 auto half bridge current control
- * Control port: Wheel control interface
- * CAD system support: March2, Mach3, KCam

DB 25 Connector Pin layout




PIN1	PIN2	PIN3	PIN4	PIN5	PIN6	PIN7	PIN8	PIN9	PIN10
CKE	CKX	CWX	CKY	CWY	CKZ	CWZ	CKA	CWA	DIN1
E STEP	X STEP	X DIR	Y STEP	Y DIR	Z STEP	Z DIR	A STEP	A DIR	Limit1
PIN11	PIN12	PIN13	PIN14	PIN15	PIN16	PIN17	PIN18-25		
DIN2	DIN3	DIN4	Exp	N/A	EN	RLY	GND		
Limit2	Limit3	Limit4	Expansion	N/A	Enable	Relay	Ground		

Board layout and motor type




2 phases, 4 phases stepping motor connection diagram (current 2A max)



Power Supply

Power for the controller is DC 12~32V. To ensure smooth movement, the power supply should be at least 10A or higher current. DC24V, 15A is recommended.



Home Limit and Emergency Stop Input

Note: All Limit Input are Active Low *

IN1 = Emergency Stop

IN2 = X limit trigger

IN3 = Y limit trigger


IN4 = Z limit trigger

GND= Ground

Relay


N.O. = Normally Open

N.C. = Normally Closed




Auxiliary Output port

This port is dedicated to all outputs and it is controllable by Mach3. The pin# is corresponding to the pin number on the parallel port.



Resolution/ Speed Setting for X,Y,Z Stepping Motor

Note: D1=1, D2=2, M1=3, M2=4



Current Attenuation and Resolution


Current attenuation setting is used to adjust overshoot or undershoot level for a motor

D1	D2	Attenuation Level	M1	M2	Resolution
DIP #1	DIP #2		DIP #3	DIP #4	
ON	ON	100%	ON	Off	1/16
OFF	ON	50%	OFF	OFF	1/8
ON	OFF	25%	OFF	ON	1/2
OFF	OFF	0%	ON	ON	1

Current Adjustment:


T1	T2	Current
Off	Off	2.5A~3A
On	Off	1.8A~2.25A
On	On	1.25A~ 1.5A
Off	On	0.65A~0.75A


Note: there are three DIP switches, one per axis, dedicated for motor current adjustment.




Basic MACH3 Setup

Note: some parameters are in default setting without affecting the output







Mach3 CNC Control Application

File Config View Wizards Operator Help

Program Run Alt-1 MDI Alt-2 ToolPath Alt-4 Offsets Alt-5 Settings Alt-6 Diagnostics Alt-7 MILL->G15 G1 G17 G40 G20 G90 G94 G54 G49 G9?

REF A Zero X +2.5000 Scale +0.0500
Zero Y -0.2500 Scale +0.0500

Tool:0 Job Display

G40 G49 G54 (tool_name: D1) G00 X0. Y-25 M03 Z5.

File: C:\Mach3\G...

Cycle Start <Alt-R> Feed Hold <Spc> Stop <Alt-S>

Run From Here Flood Ctrl-F Auto Tool Zero Remember Return Elapsed 00:00:07 Jog ON/OFF Ctrl-Alt-J

Units/Rev 0.00 Increment 10

On/Off MultiPass L (Loop) +0 Times on M30 Z Inhibit +1.000 Lower Z Inhibit by +0.0000 on each pass

History Clear Status: tool_name: D1 RPM=2200 Profile: Mach3Mill

start Mach3 CNC Control A... Ports and Pins - Paint EN 1:19 PM


Engine Configuration... Ports & Pins


Port Setup and Axis Selection | Motor Outputs | Input Signals | Output Signals | Encoder/MPG's | Spindle Setup | Mill Options

Signal	Enabled	Port #	Pin Number	Active Low	Emulated	HotKey
X ++	<input checked="" type="checkbox"/>	0	0	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	0
X --	<input checked="" type="checkbox"/>	0	0	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	0
X Home	<input checked="" type="checkbox"/>	0	0	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	0
Y ++	<input checked="" type="checkbox"/>	0	0	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	0
Y --	<input checked="" type="checkbox"/>	0	0	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	0
Y Home	<input checked="" type="checkbox"/>	0	0	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	0
Z ++	<input checked="" type="checkbox"/>	0	0	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	0
Z --	<input checked="" type="checkbox"/>	0	0	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	0
Z Home	<input checked="" type="checkbox"/>	0	0	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	0
A ++	<input checked="" type="checkbox"/>	0	0	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	0
A --	<input checked="" type="checkbox"/>	n	n	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	n


Pins 10-13 and 15 are inputs. Only these 5 pin numbers may be used on this screen

OK Cancel Apply






Note: this is a default setting.



Note: this is a default setting.



Note: this is a default setting.

Please go to Mach3 website <http://www.machsupport.com/> to get more update information. We don't support Mach3 or other 3rd software.

www.LightObject.com